MEMO TO FILE 520 West Commercial

This office conducted a walk through inspection of the former Performance Parts Building at 520 West Commercial with, and at the request of Jim Webb, Springfield Community Development.

The Community Development program may loan money on this The building contained several empty 55 gallon drums and several 55 gallon drums of what appeared to be used There are two tractor trailers parked behind the Under the trailers are several more drums of what business. appears to be used motor oil and grease. An area greater than 100 square feet under the trailers is stained with used motor oil. As was explained to Mr. Webb, the standard practice for cleanup of used motor oil contaminated soil is the analysis for Extraction Procedure (EP) metals, and submittal of the analytical results to the Missouri Department of Natural Resources for a special waste disposal permit so the material can be disposed of in the local landfill. The contact person at the Springfield Regional Office of the Mo. D.N.R. is Judy Dill, 837-6950.

Steve Short cc Jim Webb file